

SERVICE PARTS LIST FOR MITSUBISHI ELECTRIC REFRIGERATION SYSTEMS:HOT WATER HEAT PUMP UNIT

Series : CAHV-P•YB-HPB(-BS)

REVISED

Sept. 2023




BWE01503B

INDEX
CAHV-P500YB-HPB CAHV-P500YB-HPB-BS

Part information update day : **2023/09/14**

Please change the old catalog (issued Mar. 2020, No.BWE01503A) to this new catalog.
Content of revision : Some of parts are changed.







*1: Each unit requires 126 H screws (Part No. 159).
*2: Each unit requires 36 WFT screws (Part No. 161).


No.	Part No.	Part Name	Spec.	CAHV-P500YB-HPB	CAHV-P500YB-HPB-BS					Dwg. No.	Notes for the models	Revision info.
101	R11 019 626	Pillar LF		1						KB02A011G07		
102	R11 020 626	Pillar LF	BS	1						KB02A011G08		
103	R11 014 626	Pillar RF		1						KB02A012G07		
104	R11 015 626	Pillar RF	BS	1						KB02A012G08		
105	R63 002 627	Pillar B		2						KB02A013G07		
106	R63 003 627	Pillar B	BS	2						KB02A013G08		
107	R63 038 162	Frame assy L		2						KD00G100G01		
108	R63 040 162	Frame assy L	BS	2						KD00G100G02		
109	R63 039 162	Frame assy R		2						KD00G101G01		
110	R63 041 162	Frame assy R	BS	2						KD00G101G02		
111	R63 001 216	Frame assy B		2						KB00C162G10		
112	R63 002 216	Frame assy B	BS	2						KB00C162G11		
113	R63 004 668	Frame F		2						KB02J208H01		
114	R12 036 215	Frame FB	BS	2						KB02J208G03		
115	R63 013 111	Frame assy MU		2						KB00C887G01		
116	R63 014 162	Frame assy MU	BS	2						KB00C887G07		
117	R12 024 215	Frame assy MB		2						KC00G639G01		
118	R12 026 215	Frame assy MB	BS	2						KC00G639G03		
119	R63 4H6 118	Fan guard		2	2					KB25A008H08		Chg.
120	R61 095 690	Cover piping	R2	2						KB02L001G11		Chg.
121	R61 094 690	Cover piping	R2 BS	2						KB02L001G14		Chg.
122	R12 007 669	Panel assy FU		2						KN00G568G07		
123	R12 040 661	Panel assy FU	BS	2						KN00G568G08		
124	R61 003 652	Panel assy FB		1						KB02B392H04		
125	R61 004 652	Panel assy FB	BS	1						KB02B392G06		
126	R61 157 651	Panel assy FBL		1						KB02J308H02		
127	R61 162 651	Panel assy FBL	BS	1						KB02J308G03		
128	R63 004 611	Fin guard B		2	2					KB07T208G01		
129	R61 007 611	Fin guard LR		2	2					KB07C043G04		Chg.
130	R12 001 626	Pillar B(R)		1						KC02B363G05		
131	R12 013 626	Pillar B(R)	BS	1						KC02B363G06		
132	R12 002 626	Pillar B(L)		1						KC02B363G07		
133	R12 012 626	Pillar B(L)	BS	1						KC02B363G08		
134	R12 003 626	Pillar RF		1						KC02B338G09		
135	R12 007 626	Pillar RF	BS	1						KC02B338G10		
136	R12 004 626	Pillar F(L)		1						KC02B337G13		
137	R12 008 626	Pillar F(L)	BS	1						KC02B337G14		
138	R12 005 626	Pillar F(R)		1						KC02B337G15		
139	R12 009 626	Pillar F(R)	BS	1						KC02B337G16		
140	R12 014 626	Pillar assy LF		1						KC00H676G01		
141	R12 015 626	Pillar assy LF	BS	1						KC00H676G02		
142	R12 075 661	Panel B		1						KC02L798G01		
143	R12 076 661	Panel B	BS	1						KC02L798G02		
144	R63 L59 060	Guard fixed plate		2	2					W893727H04		Chg.
145	R12 009 669	Panel M		1						KC02G150G07		

[illegible]



*3: When part 213 (TH11 through TH13, and TH16) or part 218 is replaced, replace part 230 as well.

[illegible]



CAHV-P500YB-HPB
CAHV-P500YB-HPB-BS

CONTROL BOX PARTS

[illegible]

mitsubishi electric corporation

BWE01503B (20230930)