




# SERVICE PARTS LIST FOR MITSUBISHI ELECTRIC PACKAGED AIR-CONDITIONERS


Series : CMB

Oct. 2025  
BWE025340


INDEX
CMB-M104NU-MA-SV
CMB-M106NU-MA-SV
CMB-M108NU-MA-SV
CMB-M1012NU-MA-SV
CMB-M104NU-MB-SV
CMB-M108NU-MB-SV



\* Check valve do not set service parts.  
Because, the quality securing of them  
when exchanging parts is difficult.






113 . 115 . 120




A

\* Part No. 115 (Linear expansion valve) is  
difficult to be replaced individually because  
it is close to the peripheral parts.  
It is recommended to replace No. 113 or  
114 (Pipe assy LEV), which includes Part No. 115.






\* Check valve do not set service parts.  
Because, the quality securing of them  
when exchanging parts is difficult.



213 . 216 . 221      214 . 216 . 221





215 . 216 . 221



\* Part No. 216 (Linear expansion valve) is  
difficult to be replaced individually because  
it is close to the peripheral parts.  
It is recommended to replace No. 213 or  
214 or 215 (Pipe assy LEV), which includes  
Part No. 216.

B





\* Check valve do not set service parts.  
Because, the quality securing of them  
when exchanging parts is difficult.




314 . 315 . 320


\* Part No. 315 (Linear expansion valve) is difficult to be replaced individually because it is close to the peripheral parts. It is recommended to replace No. 312 or 313 or 314 (Pipe assy LEV), which includes Part No. 315.

C






\* Check valve do not set service parts.  
Because, the quality securing of them  
when exchanging parts is difficult.





\* Part No. 417 (Linear expansion valve) is  
difficult to be replaced individually because  
it is close to the peripheral parts.  
It is recommended to replace No. 413, 414,  
415 or 416 (Pipe assy LEV), which includes  
Part No. 417.






\* Check valve do not set service parts.  
Because, the quality securing of them  
when exchanging parts is difficult.




513  
514  
518  
E

\* Part No. 514 (Linear expansion valve) is  
difficult to be replaced individually because  
it is close to the peripheral parts.  
It is recommended to replace No. 512 or 513  
(Pipe assy LEV), which includes Part No. 514.






\* Check valve do not set service parts.  
Because, the quality securing of them  
when exchanging parts is difficult.




\* Part No. 614 (Linear expansion valve) is  
difficult to be replaced individually because  
it is close to the peripheral parts.  
It is recommended to replace No. 611 or 612 or  
613 (Pipe assy LEV), which includes Part No. 614.



CMB-M104,M106NU-MA-SV,CMB-M104NU-MB-SV



CMB-M108,M1012NU-MA-SV,CMB-M108NU-MB-SV





**mitsubishi**  
**electric**  
**corporation**

---

BWE025340 (20251031)