


SERVICE PARTS LIST FOR MITSUBISHI ELECTRIC REFRIGERATION SYSTEMS:HOT WATER HEAT PUMP UNIT

Series : CAHV-R136TAU(-BS)

Dec. 2025

BWE025540

INDEX
CAHV-R136TAU CAHV-R136TAU-BS




*1: Each unit requires 26 WFT screws (Part No. 147).

*2: Each unit requires 79 H screws (Part No. 148).

*3: Each unit requires 8 WFT screws (Part No.149).

No.	Part No.	Part Name	Spec.	CAHV-R136TAU	CAHV-R136TAU-BS					Dwg. No.	Notes for the models	Revision info.
101	R63 052 652	Panel R		1						KB02A370G05		
102	R63 053 652	Panel R	BS	1						KB02A370G06		
103	R63 050 652	Panel L		1						KB02A369G07		
104	R63 051 652	Panel L	BS	1						KB02A369G08		
105	R61 022 626	Pillar assy MF		1						KD00R845G09		
106	R61 023 626	Pillar assy MF	BS	1						KD00R845G10		
107	R61 030 626	Pillar assy MB		1						KD02M109G01		
108	R12 035 626	Pillar assy MB	BS	1						KD02M109G03		
109	R61 061 162	Frame assy F		1						KD00L182G03		
110	R61 094 162	Frame assy F	BS	1						KD00L182G07		
111	R61 012 160	Frame assy B		1						KJ00C487G01		
112	R61 013 160	Frame assy B	BS	1						KJ00C487G02		
113	R61 175 162	Frame assy LR		1						KV00R705G01		
114	R61 176 162	Frame assy LR	BS	1						KV00R705G02		
115	R61 098 162	Frame assy L		1						KJ00C488G03		
116	R61 099 162	Frame assy L	BS	1						KJ00C488G04		
117	R61 012 499	Plate HE X assy		1						KJ00C692G01		
118	R61 013 499	Plate HE X assy	BS	1						KJ00C692G02		
119	R12 049 215	Frame MT		1						KC00U520G01		
120	R12 050 215	Frame MT	BS	1						KC00U520G02		
121	R12 051 215	Frame assy M		1						KW00G036G01		
122	R12 052 215	Frame assy M	BS	1						KW00G036G04		
123	R61 058 162	Frame MR		1						KD02G743H04		
124	R61 059 162	Frame MR	BS	1						KD02G743G02		
125	R12 047 011	Piping cover		1						KW00D349G11		
126	R12 048 011	Piping cover	BS	1						KW00D349G12		
127	R12 127 661	Panel FBL3		1						KW00D350G03		
128	R12 128 661	Panel FBL3	BS	1						KW00D350G04		
129	R12 129 661	Panel FBL2		1						KW00D348G05		
130	R12 130 661	Panel FBL2	BS	1						KW00D348G06		
131	R12 131 661	Panel FBL1		1						KW00D347G03		
132	R12 132 661	Panel FBL1	BS	1						KW00D347G04		
133	R61 212 651	Panel FBR		1						KB02J838H04		
134	R61 213 651	Panel FBR	BS	1						KB02J838G06		
135	R61 177 651	Panel FU		2						KB02J839H01		
136	R61 178 651	Panel FU	BS	2						KB02J839G02		
137	R61 005 119	Bell mouth		2	2					KB25A367H04		
138	R11 003 009	Fan guard		2	2					KB25V019H04		
139	R61 009 669	Plate Fan guard		8	8					KD02D205H03		
140	R61 010 611	Fin guard B		2	2					KB07N272G01		
141	R61 016 140	Base fan		4						KD02D026H01		
142	R61 017 140	Base fan	BS	4						KD02D026G04		
143	R12 005 941	Motor	10P 920W 200V	2	2					KC61J778G02		
144	R61 001 300	Fan		2	2					KB25A009H05		
145	R63 4H6 122	Box nut	M12 CH	2	2					P552000X01		

[illegible]




CAHV-R136TAU
CAHV-R136TAU-BS


FUNCTIONAL PARTS

[illegible]

*4 When part 309 is replaced, replace part 311 as well.



[illegible]



[illegible]

mitsubishi electric corporation

BWE025540 (20251231)